

AMPHORA RETAIL CENTER

Vienna, Virginia

Client: Rollin Road Restaurant

BC provided engineering and surveying services for a commercial/retail infill site in downtown Vienna. An extensive outfall analysis was required to verify the adequacy of the existing storm drainage system. This eliminated the need for an onsite storm water management facility.

